

## Отчет о диагностике автомобиля

### Информация о а/м

Номерной знак:

Год выпуска:2020

Серии а/м:SERES

Модель:SF5

VIN:LM8F7B69XLA000888

Время испытания:2024-06-14 11:23:11AM

Версия ПО а/м:V10.50

Версия диагностической прикладной программы:V2.00.027

Операция пользователя:SF5 > Health Report

SF5 > Health Report > Gateway(GTW)

SF5 > Health Report > InstrumentCluster(IC)

SF5 > Health Report > BatteryManagementSystem\_REV(BMS)

### Диагностический код неисправности

| Диагностич | Описание                               | Состояние | Система                          |
|------------|----------------------------------------|-----------|----------------------------------|
| U015687    | IVI loss communication                 | History   | VehicleControlUnit_EV(VCU)       |
| P1000F7    | OBC short to ground error              |           | VehicleControlUnit_EV(VCU)       |
| P1000F8    | OBC short to power error               |           | VehicleControlUnit_EV(VCU)       |
| P1000F5    | OBC input under voltage error          |           | VehicleControlUnit_EV(VCU)       |
| U015687    | IVI node is missing                    | History   | VehicleControlUnit_REV(VCU)      |
| P1000F7    | OBC short to ground error              | History   | VehicleControlUnit_REV(VCU)      |
| P1000F8    | OBC short to power error               | History   | VehicleControlUnit_REV(VCU)      |
| P1000F5    | OBC input under voltage error          | History   | VehicleControlUnit_REV(VCU)      |
| U029387    | Lost communication with VCU            | History   | BatteryManagementSystem_REV(BMS) |
| U019887    | Lost communication with Tbox           | History   | BatteryManagementSystem_REV(BMS) |
| U015187    | Lostcommunicationwith ACU              | History   | BatteryManagementSystem_REV(BMS) |
| P125200    | CC disconnect                          | History   | BatteryManagementSystem_REV(BMS) |
| U015687    | Lost IVI                               | History   | AirConditioningSystem(AC)        |
| U015687    | Lost Communication with IVI            | History   | MultiplePurposeCamera(MP C)      |
| U014087    | Lost Communication with BCM            | History   | DriverSeatModule1(DSCU)          |
| U015687    | Lost Communication with IVI            | History   | DriverSeatModule1(DSCU)          |
| U015687    | Lost Communication with IVI            | History   | DrivingRecorder(DVR)             |
| U015687    | Lost communication with IVI            | History   | ElectronicPowerSteering(EPS)     |
| U120287    | Lost communication with MPC            | History   | ElectronicPowerSteering(EPS)     |
| U032187    | Lost Communication With ASC            |           | Gateway(GTW)                     |
| U015687    | Lost Communication With IVI            | History   | Gateway(GTW)                     |
| U015687    | Lost Communication with IVI            | History   | Head-updisplay(HUD)              |
| C1F0208    | iBooster System shutdown error         | History   | SmartBoosterAssembly(iboos ter)  |
| B206400    | CAN transceiver fault                  | History   | InstrumentCluster(IC)            |
| U015687    | Lost communication with IVI set        | History   | InstrumentCluster(IC)            |
| U014087    | loss of communication with BCM(0x2C1)  | History   | PowerOperationTailgate(POT )     |
| U015687    | loss of communication with IVI(0x75)   | History   | PowerOperationTailgate(POT )     |
| U014087    | Lost Communication With BCM            | History   | TelematicsBox(T-BOX)             |
| U015687    | Lost communication with IVI chassisSet | History   | ElectronicStabilityControl(ES C) |
| U141A08    | VLC related signal invalid             | History   | ElectronicStabilityControl(ES C) |
| U014087    | Lost Communication with BCM            | History   | PassengerSeatControlUnit(PS CU)  |

|         |                              |         |                                |
|---------|------------------------------|---------|--------------------------------|
| U015687 | TIMEOUT IVI                  | History | MiddleRangeRadar(MRR)          |
| U140381 | INVALID ESC                  | History | MiddleRangeRadar(MRR)          |
| U015687 | TIMEOUT IVI                  | History | MiddleRangeRadar_Rear1(MRR_R1) |
| U015687 | TIMEOUT IVI                  | History | MiddleRangeRadar_Rear2(MRR_R2) |
| B206400 | CAN transceiver fault        | History |                                |
| U019887 | Lost communication with Tbox | History |                                |
| U015187 | Lostcommunicationwith ACU    | History |                                |